

uBoone Operations - Necessary Maintenance #8799

Understand operations of liquid level probes

05/14/2015 02:34 PM - Matthew Touns

<b>Status:</b>	New	<b>Start date:</b>	05/14/2015
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	Tia Miceli	<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Description</b>			
The upstream liquid level probe does not have its shield installed because it did not fit in the port. We should investigate whether this can produce any unwanted noise by procuring an additional liquid level probe and transmitter and testing it.			

History

#1 - 05/14/2015 03:22 PM - Matthew Touns

- Assignee set to Tia Miceli